



Drives & Nutrunners



Paragon now offers Atlas Copco Power Focus repairs. All controllers will have the power supply and memory battery replaced.

All the controller boards are tested and calibrated to full OEM specifications before leaving Paragon.

Paragon also has the capabilities to test all S4, S7 and S9 nutrunners. Upon repair before leaving Paragon, all nutrunners are also tested and calibrated to full OEM specs.

DRIVES

ATLAS COPCO

Tenor DS

D302-DS7

D312-DS7

ATLAS COPCO

Tenor S (2000)

Power Focus 2101-S4

Power Focus 2102-S4

Power Focus 2101-S7

Power Focus 2102-S7

Power Focus 2102-S9

NUTRUNNERS

ATLAS COPCO

Tenor DS

ETV-DS7

ETF-DS7

ETD-DS7

ETP-DS7

ETC-XXX

ETO-XXX

ATLAS COPCO

Tenor S

ETV-XXX

ETF-XXX

ETD-XXX

ETP-XXX

ETC-XXX

ETO-XXX

TECH MOTIVE

CS7000

17710-XXXX

17711-XXXX

27711-XXXX

27712-XXXX

27713-XXXX



5775 Ten Mile Road
Warren, MI 48091
phone: (800) 229-5350
fax: (800) 229-5375
www.paragontech.com



1100 South Service Rd., #103
Stoney Creek, ON., Canada L8E 0C5
phone: (800) 567-3786
fax: (800) 229-5375
www.paragoncanada.ca



2919 Interstate Street
Charlotte, NC 28208
phone: (800) 756-9150
fax: (800) 229-5375
www.paragonatlantic.com



82 Corporate Park Drive
Henderson, NV 89074
phone: (800) 756-9160
fax: (800) 229-5375
www.paragonpacific.net